



Sinter Plant Services

Address: Portion 70 445 JQ
R513 Road
(Between Hartbeespoort & Brits)

Phone: 012 001 4999

Email: services@spsplant.com

Reg. No.: 2002/68866/23



MAINTENANCE INSPECTION

Inspection No.: 00001

Company: Jona Solutions - Hartenbos

Location: GPS: ,

Inspector: Jorge Jardim

Date: 16 April 2021

Part No: Filter 01 Jorge

Inspector No.: 082 338 2113

PARTS REQUIRED

Part No.	Description	Quantity
CAR-BAT-12V	12 Volt Battery	1
CAR-TYR-002	Car Tyre	1

INSPECTION QUESTIONNAIRE

No.	Item	Value
1.	Ceramic 001	2021-04-15
2.	Ceramic 001	41 Pa
3.	Pressure	1 bar
4.	Condition	Acceptable bar

1. Ceramic 001



2. Ceramic 001





Sinter Plant Services

Address: Portion 70 445 JQ
R513 Road
(Between Hartbeespoort & Brits)

Phone: 012 001 4999

Email: services@spsplant.com

Reg. No.: 2002/68866/23



3. Pressure



4. Condition



Signed by Inspector: Jorge Jardim (082 338 2113)