



Sinter Plant Services

Address: Portion 70 445 JQ
R513 Road
(Between Hartbeespoort & Brits)

Phone: 012 001 4999

Email: services@spsplant.com

Reg. No.: 2002/68866/23



MAINTENANCE INSPECTION

Inspection No.: 00002

Company: APT

Location: GPS: -26.270759299999998,28.1122679

Inspector: Gert van Oordt

Date: 16 April 2021

Part No: Filter002

Inspector No.: 0827478821


PARTS REQUIRED

Part No.	Description	Quantity
CAR-BAT-12V	12 Volt Battery	1

INSPECTION QUESTIONNAIRE

No.	Item	Value
1.	Ceramic 001	1970-01-01
2.	Ceramic 001	40 Pa
3.	Pressure	1 bar
4.	Condition	looks bad bar

3. Pressure





Sinter Plant Services

Address: Portion 70 445 JQ
R513 Road
(Between Hartbeespoort & Brits)

Phone: 012 001 4999

Email: services@spsplant.com

Reg. No.: 2002/68866/23



Signed by Inspector: Gert van Oordt (0827478821)