



Sinter Plant Services

Address: Portion 70 445 JQ
R513 Road
(Between Hartbeespoort & Brits)

Phone: 012 001 4999

Email: services@spsplant.com

Reg. No.: 2002/68866/23



MAINTENANCE INSPECTION

Inspection No.: 00013

Company: Jona Solutions - Hartenbos

Location: GPS: ,

Inspector: Jorge Jardim

Date: 13 April 2021

Part No: A100 Self Cleaning Filter J01

Inspector No.: 082 338 2113

PARTS REQUIRED

*** NO PARTS REQUIRED ***

INSPECTION QUESTIONNAIRE

Item	Value
Back wash pressure before water filter.	37
Date of last wash.	2021-04-12
Vacuum pump temperature.	55
Vacuum pipes and clamps condition.	10
Housekeeping	Done.
Vacuum gauge reading.	30

Signed by Inspector: Jorge Jardim (082 338 2113)