



Sinter Plant Services

Address: Portion 70 445 JQ
R513 Road
(Between Hartbeespoort & Brits)

Phone: 012 001 4999

Email: services@spsplant.com

Reg. No.: 2002/68866/23



MAINTENANCE INSPECTION

Inspection No.: 00021

Company: APT

Location: GPS: -34.1113541,22.1180766

Inspector: Gert van Oordt

Date: 15 April 2021

Part No: Pen Jorge 01

Inspector No.: 0827478821

PARTS REQUIRED

Part No.	Description	Quantity
CAR-TYR-002	Car Tyre	4

INSPECTION QUESTIONNAIRE

Item	Value
What is the backwash pressure	123



Signed by Inspector: Gert van Oordt (0827478821)